



Working at the Nikon C2 under special safety measures


- Wear always **lab coat, fresh gloves, mask** and **safety glasses**.
- Use always **fresh plastic wrap** for this procedures!
- Wrap foil around **keyboard** and **mouse** and **eyepieces**
- Remove **wrap at the end of the session** and **clean with 70% ETOH!**
- Take off gloves and lab coat only when leaving the room!

Lab coat
fresh gloves
mask
safety glasses



After your work – **remove all the foils** and throw them (crumbled up) in the **yellow bin**, **clean** carefully **table surface** and **focus knobs** with paper tissue wetted **with 70% ETOH** (still wear your gloves).

Take off gloves and lab coat only when leaving the room!



Please keep to these guidelines to ensure a safe working environment for all - thank you very much!

your LIC team